

Hammock Oaks

FIELD REPORT



April 2024

HAMMOCK OAKS



• Entire brick system is shifting. Will need to be reset.



• Microwave was replaced at the Guardhouse.

Gate Repairs



DML Security Systems

18495 South Dixie Hwy #264 Cutter Bay, FL 33157 (786) 899-2256 kevin@dml-security.com

WORK ORDER REPORT



Display name Governmental Management Services-South Florida, LLC

Customer Type Commercial

Custom Id 86

Company name Governmental Management Services-South Florida, LLC

Pricing Tier Tier 1

Description



Service : Hammock Oaks taxing district (C/O GMS) : old cutler road and campana ave, Miami, FL 33156, United States

Address Type Service

Street address old cutler road and campana ave

Apt/Suite

City, State ZIP Miami, FL 33156, United States

Description

 Contact
 Phone
 Type

 Paul Winkeljohn
 -Not Set

Service Request #4181

Summary Hammock Oaks (Cap2d & Vis Operator)2-1-24

Date Requested 02/01/2024

Description

Created 02/01/2024 08:09 AM

Customer Governmental Management Services-South Florida, LLC

Service Request Notes

Date User Note

02/01/2024 08:09 AM Scott Lawson Work Order #4181-1 was created with status Unassigned

02/01/2024 08:10 AM Scott Lawson Work Order #4181-1 status was changed from Unassigned to Incomplete

02/01/2024 08:10 AM Scott Lawson Work Order #4181-1 was assigned from "-Not Set." to "Ruben Hernandez"

02/01/2024 08:10 AM Scott Lawson Work Order #4181-2 was created with status Incomplete

02/01/2024 07:55 PM Ruben Hernandez Work Order #4181-1 status was changed from Incomplete to Complete - Return Visit Required

02/02/2024 05:31 PM DML Tech DML Tech Work Order #4181-2 status was changed from Incomplete to Complete - Return Visit Required

visit Redu

RAZOTSYNC. © 2024 RazorSync.com. All rights reserved. All other trademarks are the property of their respective owners.



Governmental Management Services-South Florida, LLC

5385 N. Nob Hill Road Sunrise, FL 33351

02/02/2024 05:45 PM DML Tech DML Tech Work Order #4181-2 status was changed from Complete - Return Visit Required to incomplete 02/02/2024 07:17 PM Ruben Hernandez Work Order #4181-1 status was changed from Complete - Return Visit Required 02/05/2024 10:50 AM Kevin Wimberly Work Order #4181-2 status was changed from incomplete to Complete 02/05/2024 11:02 AM Kevin Wimberly Work Order #4181-1 status was changed from Complete to Invoiced 02/05/2024 11:02 AM Kevin Wimberly Work Order #4181-2 status was changed from Complete to Invoiced 02/19/2024 02:31 PM Kevin Wimberly Payment #7252 in amount of \$3,927.75 was received for Invoice #4181 02/19/2024 02:31 PM Kevin Wimberly Invoice #4181 was paid in full

Work Order #4181-1

Hammock Oaks (Cap2d & Vis Operator)2-1-24 Description

Technician Ruben Hemandez

Status Invoiced

Start 02/01/2024 08:00 AM 02/02/2024 05:00 PM End

Invoicing Memo

Due to recent service the visitor barrier arm operator had cracks forming on the bottom of the chassis; the unit was removed and new anchors were installed; however the unit has too much shake and worbble due to the cracks in the chassis which causes the unit to go into IRS mode and the possibility of the arm breaking off. New operator to be installed, and the PMSA discounts to be provided per an active PMSA / KW approval.

DML to upgrade existing access control system to Liftmaster Cap2d (cloud based 2 door controller), and managed via Liftmaster MyQ Portal.

New Panel Installed, configured, and programmed; management to be sent remote

*** Discounts provided per KW via Liftmaster / Distribution Promo and DML PMSA

*** Liftmaster MyQ Portal Hosting t be included in PMSA Agreement; billed quarterly

	Service Items				
Name	1	Description	Unit Type	QTY	Taxable
NOTE	5	The below service is Partially covered under an active preventative maintenance or service agreement	Item	1	N
CP-M/	ATDCBB3	Liftmaster Full Cabinet Commercial Barrier Arm Tower	Item	1	N
CP-NF	P2-12-24AC-DC	Loop Detector, Low Voltage 12/24 AC/DC	Item	1	N
Cp-80	24	Loop Det. 11 Pin Harness 4' mesh sleeve 11-Pin Loop Detector Harness	Item	1	N
Materi	als	Conduit, J-Boxes, Fittings, Connectors, Etc	Item	1	N
Install		Install, Configure, and Program the above	Item	1	N
Trip C	harge	Travel: Includes gas, tolls, and parking	Item	1	N
DML-F	PMSA-DC	Equipment Discount: Per an active preventative maintenance or service agreement	Item	1	N
DML-F	PMSA-DCL	Labor or Service Discount: Per an active preventative maintenance or service agreement	Item	0.25	N
NOTE	S	DML to upgrade existing access control system to Liftmaster Cap2d (cloud based	Item	1	N

HAMMOCK OAKS

FIELD DIVISION REPORT Paul Winkeljohn Phone 954-721-8681

DML-PMSA	The below service is Partially covered under an active preventative maintenance or service agreement	Item	1	N
CP-CAP2D	CAP2D: Connected Access Portal-2 Dr Controller LiftMaster-Cloud Based, Credentialed Access Control, 12VDC, 1.5A minimum	Item	1	N
Materials	Conduit, J-Boxes, Fittings, Connectors, Etc	Item	1	N
Trip Charge	Travel: Includes gas, tolls, and parking	Item	1	N
Install	Install, Configure, and Program the above	Item	0.75	N
DML-PMSA-DC	Equipment Discount: Per an active preventative maintenance or service agreement	Item	1	N
DML-PMSA-DCL	Labor or Service Discount; Per an active preventative maintenance or service agreement	Item	0.4	N
DML-PMSA-DCL	Trip Discount: Per an active preventative maintenance or service agreement	Item	1	N

Service Forms



Attachments

Title
PDF Invoice 4181
PDF Invoice 4181
Bracket and hardware
fastened down

File Name Invoice 4181.pdf Invoice 4181.pdf

c5761082-0f2e-490e-8aaa-8db1269c94a7.jpg





bb4dbb55-94d5-40b9-a5e8-e9c0655a38c0.jpg



Gate locked after installation was completed

185d83a6-a2bf-4048-8a00-7e503952874b.jpg



Factory key removed and turned into the GH

828e42cf-9ce6-4f3e-boca-13b8a7b3a0a1.jpg





71423c9d-f2ef-4c62-852c-a7d9b3b44e0a.jpg



New batteries installed and tested for back up

93b6135f-bfe6-47ce-92f2-d8ae35c18621.jpg



All splices completed and waterproofed

f0f16dee-442e-4960-82f2-01fccc4ec875.jpg



HAMMOCK OAKS

FIELD DIVISION REPORT Paul Winkeljohn Phone 954-721-8681

AC power waterproof wire nuts

d2ce8c97-bc75-417d-8c07-9f7a926c2e6a.jpg



Gear box cap air release removed

95f119b1-b0c5-4d58-bb66-7a68376a8ffc.jpg



New antenna

5a47108b-c96d-4a59-8b94-0ef24de6cf06.jpg

